

## Enabling Surface Pro 3 Dock Gigabit Ethernet drivers in Windows PE

## Enabling Surface Pro 3 Dock Gigabit Ethernet drivers in Windows PE

## Step 5:

### Rebuild Rescue Media

When you boot into Windows PE the network adapter should be detected.

## Alternatively.

### Step 1:

Extract the contents of **Surface Gigabit Ethernet Adapter.zip** to the rescue media USB drive.

### Step 2:

Within Windows PE open a command prompt and navigate using "**CD**" to the folder on your USB drive that contains the drivers.

### Step 3:

Type **drvload msu30x64w8a.inf** and press return.

Your network adapter should now be detected.